Fd. Brass Cap 1s Down. In Position Accepted By Harrington (G.L.O. Surveyor. During Dependent Re-Survey Of 1919. Accepted For This Survey As The N.W. Cor. Sec. 33.

Note
Distribution Power Line Varies From 0.5' To 2.0' North Of Line From N.E. Cor Sec. to N.W. Cor Sec. As Shown Hereon.

Fd. Concr. Filled Iron Pipe Below Ground Surface For The N. ¼ Cor. Sec. 33.

Found M.C.H.B.C. In Handhole. Position Accepted By Harrington In 1919 & Others Since. The N.E. Cor. Sec. 33.

E-W. Fence Is 2.4' N. Of Line At Cor.

East-West Fence Is 0.2' N. Of Line At East End.

(Assumed Brg.) - S. 87°53'00" E., 2726.27'

℄ Concr. Lined Ditch Is 5.3' North Of Line At W. End.

1285.21'

1407.99'

Pole For Power Line B.C.H., 0.5' N. of ¼ Cor.

℄ Concr. Lined Ditch Is 5.1' N. Of Line At N. ¼ Cor.

S. 87°51'02" E., 2725.26'

Pole & Tel. Pole

Residence Yard

N. 1°28'54" W., 380.03'

PARCEL "C", 11 A.

379.35'

N. 87°53'00" W., 1269.38' ~~1272.76'~~ C.G. 2/21/75

Easement

783'

N. 1°28'54" W.

516.75'

360.51'

331.92'

For Irrigation

15'

Existing Nail Site Lies Within A 75' x 75' Exception Described In Docket 6499, Page 391, M.C.R.

PARCEL "D", 4 A.

N. 40°00'25" W., 500.00'

Existing

East Line Shed Post 1½ West

S.W. Cor. Horse Shed 0.2' E. Of Line

N. 43°23'56" W., 47.73'

N. 43°36'20" W., 126.06'

N. 48°09'56" W., 95.34'

N. 54°06'34" W., 44.91'

N. 61°06'34" W., 68.23'

N. 75°04'39" W., 61.76'

N. 79°47'29" W., 240.39'

N. 79°47'29" W., 336.27'

Dirt

Small Concr. Lined Ditch Apparently Dead Ends Here

Other Existing Improvements In This Area Not Shown Hereon

Note: South Line Of Nail Site Is Approx. 680.5' Of N.W. Cor. Sec. 33.

S. 1°27'33" E.

Canal

PARCEL "B", 5 A.

S. 0°54'25" W., 632.65'

PARCEL "A", 5 A.
Dkt. 8096, P. 474

680.00'

Existing

S. 0°54'25" W., 1059.35'

15'

N. 0°36'24" W., 1210.63'

℄ New State Canal

End Canal. Begin Private Ditch

Existing Fences, Etc. Not Shown Hereon.

Road ℄

ST JOHNS CANAL

Fence Described In Deed As The South Line Of This Property

N. ¼ Cor. (See Sheet 2)

North-South Mid-Sec. Line

This Point Traverse Control Only. Not A Property Cor.

REPORT OF SURVEY

FOR

MRS. SYBLE M. DE WITT

Route 1, Box 154 Tolleson, Arizona

Of That Portion Of The N. ½, N.W. ¼ Sec. 33, T.1N., R.1E., G.&S.R.B.&M., Maricopa County, Arizona, Shown Hereon, Being Also A Portion Of That Parcel Of Land Described In Docket 335, Page 312, M.C.R.

N

Scale, 1" = 100'

LEGEND

○ = ½ I.D. Iron Pipe Tagged L.S. 1681, Set This Survey
Overhead Utilities Pole
Anchor
Fence
D Earth Type Ditch
CD Concrete Lined Ditch
C.M. - Calc. From Measurement

Note: All Bearings And Distances Shown Hereon Are Direct Measurement Unless Otherwise Noted.

This will certify that the field work shown hereon was done between Feb. 20, 1970 and June 16, 1970 under my supervision.

Eugene [illegible]
RLS 1681
7/21/70
Arizona U.S.A.

DIN # 55756-1/2
APLS

ARIZONA SURVEYING SERVICE
5704 N. 27th Ave Phoenix, Arizona
Drawing No. L-70-1580 Phone - 277-3904
Sheet 1 of 2 Sheets