Found pipe
N¼ Cor. Sec. 30

ROAD

S.88°-08'E (Assumed) 1367.50

Set pipe
NE Cor NW¼NE¼

33

Fence

33

Set Pipe 3ft
North of property
Line

set pipe on
Property Line

Yavapai County Savings Bank

N.4°-05'-30"W. 1412.2 (¼¼ Cor to N¼ Cor)

General American Life Insurance Co.
NW¼ NE¼ Sec 30 1N 2E 44.37 Acres

S.3°-41'-30"E. 1438.9 (¼¼ Cor. to ¼¼ Cor.)

Fence

King

Fence

Found pipe

set pipe in fence
108.6 from ¼¼ Cor.

N.27°-52'-30"W. 228'

Set pipe
SW. Cor. NW¼ NE¼

Fence

72'

set pipe in fence
138.0 from ¼¼ Cor.

Spur lock

N86°-58'-30"W. - 1360.5

O'Shields

71.7

Set pipe
SE. Cor. NW¼ NE¼

Found Stone
N.W. Cor.

Found Pipe
N¼ Cor

Found Stone
N.E. Cor.

S.89°-20'E
2640.90

S.89°-08'E
2735.00

N.0°-16'-30"W
2640.86

N.4°-05'-30"W
2824.51

2931.16

5862.31

S.85°-48'-30"E

S.85°-48'-30"E.

2837.20

2708.09

Found pipe
N¼ Cor.

N.4°-05'-30"W

3147.19

2931.16

S.3°-18'E

N

Scale 1 inch = 100 feet

Found pipe
¼¼ Cor.

S.89°-42'W

Found pipe
SE. Cor.

2649.48

SKETCH MAP OF SEC 30
SHOWING CORNERS FOUND & USED

MAP SHOWING
RESULTS OF SURVEY OF
THE N.W. ¼ OF THE NE ¼ OF SEC. 30
T1N. R 2E G & S R B & M
MARICOPA CO. ARIZONA
SURVEYED FEBRUARY 1935
FOR GENERAL AMERICAN LIFE INS. CO
F. N. HOLMQUIST - ENGINEER

DIN # 58492-1

Job 1077