Fd. Brass Cap marked T 3S R 5W | R 4W 3.24 | 3.25 9.25 | 9.30 1931 1.0' below ground surface on the west side of a 6"x6" post 3.5' high.

BLM = N.0°24'59"E., 5339.60'
CM - N.0°24'59"E., 5323.84'

Searched for the corner marked T 3S R 5W | R 4W 3.25 | 3.30 9.26 | 9.31 1931 in the Official Notes of Resurvey of T.3S., R.4W. Corner not found or reset this survey.

BLM - East, 2567.40'
CM - S.89°58'49"E., 2570.75'

Fd. Iron bar with aluminum Cap Marked 1/4 S 3/4 T, L.S.5713 with 4" Plastic tubing 6" high alongside.

BLM - N.89°13'E
M - 134.5'
BLM - 152.0'

Sec. Cor. Searched For This Survey - Not Fd.
30 | 29
31 | 32

CM - N.0°17'46"W., 1311.18'

6.10 A.

CM - S.0°08'55"W., 2435.36'

N.E.1/4, Sec.31

2620.58'

Fd. Iron Bar - Not Tagged. With 4" Plastic Tubing 6" High Alongside.

Parcel No.3

N.W.1/4, Sec.31

BLM - N.0°28'W., 2638.68'
CM - N.0°28'02"W., 2640.78'

CM - N.0°17'46"W., 1309.40'

P.I. Fence

Road Dike

Large Mesquite Trees With Wire On Them.

East 1/4 Cor. Sec. 31 Fd. In Fdn. Bronze Bottom Stamped Fd. 1/4 Point This Survey.

73.5'

Calc. BLM & CM - N.89°34'09"E., 2562.83'

Fd. Brass Cap Marked 1/4 T 3S R 5W | R 4W 5.34 | 5.35 Also found dead mesquite tree marked 1/4 5.31.BT on west face. Measured westerly, 68.5' to the Brass Cap. Fd. Brass Cap 0.5' South and 14.6' East of true position as determined by proportioning measurements taken this survey based on Bearings and Distances shown in the Official Plat and Notes of Resurvey.

Position Of Center Of Section Computed From Data This Survey and BLM Data. Cor. Not Set This Survey.
Note: Area flooded by irrigation at time of this survey. A 4" dia. plastic pipe 6" high stands 2" south and 7.1' east of position of center of section shown.

Holding Pond Under Construction

New Dyke

1332.08'
665.36'

Fd. 4" Plastic Pipe 6" High Set At West Edge New Dyke

1331.89'

CM - S.0°21'08"E., 2855.34' - (Ft. Fence to S. Line Sec.)

665.0' (Plastic Cap In Plastic Cap)

Hemp - 2.7' Hi. 3.5' High Parcel No. 2

2.26 A.

All trees of hemp pipe

N.W.1/4, S.E.1/4, Sec.31

S.W.1/4, Sec.31

Fd. South 1/4 Cor. to Cor. Fd. For North 1/4 Cor. = CM - N.0°17'46"W., 2584.73'
Fd. S.1/4 Cor. to Position of Center of Sec. = CM - N.0°17'46"W., 2664.15'

Fd. 4" Plastic Pipe 6" High Set At S.W. Cor. New Dyke.

S.89°25'05"W.

S.W.1/4, S.E.1/4, Sec.31

Existing 4 Strand Barbed Wire Fence In Good Condition.

1332.07'

133.87'

2.30 A.

Old Fence Down - wire on ground and traces of old fence post found.

Parcel No.1

BLM - S.89°46'W., 2567.40'
(Assumed) - S.89°46'00"W., CM - 2567.24'

Fd. Brass Cap Marked with marked stone alongside and mound of stone The S.W. Cor. Sec. 31 T 4S R 5W | R 4W 3.1 | 3.2 1931

BLM - N.0°17'W., 2633.20'
CM - N.0°17'02"W., 2635.31'

Fd. Brass Cap Marked 5.31 | 5.6 1931 alongside.

M - 70
BLM - 78.56'

BLM - N.89°16'E.

Note: All references to Official Notes and Plat Shown hereon refer to Book 3928 - Field Notes of the resurvey of the East, North, South and West Boundary and Subdivision Lines of Section 31, Township 3 South, Range 4 West, Gila and Salt River Base and Meridian, Arizona, Executed by Benjamin J. Kinsey and Karl L. Siebecker, U.S. Surveyors, dated October 28, 1930 and April 29, 1931 and the Official Plat of Dependent Resurvey Accepted by the Acting Assistant Commissioner, Dept. of the Interior, General Land Office, Washington D.C., on November 10, 1932 and found on file in the Office of the Bureau of Land Management, Phoenix, Arizona.

LEGEND

- Monument Found
- Corner Found or Re-Established
- Corner Not Found or Not Tagged, L.S. 5713 Set This Survey
- Corner Found - Reference Tagged, L.S. 5713 Set This Survey
- Corner Found - Reference Tagged, Other
- Corner Found - Reference Tagged, Other
- Corner Found - Reference Tagged, Other
- Calculated Point
- Corner Found - Not Tagged
- Corner Found - Not Tagged
- Corner Found - Not Tagged
- Corner Found - Not Tagged

REPORT OF SURVEY

OF

A parcel of land lying in the East 1/2, Sec. 31, T.3S., R.4W., G.&S.R.B.&M.

SCALE: 1" = 100'

Jack M. Rayner
Litchfield Park, Arizona

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE BY ME OR UNDER MY DIRECT SUPERVISION AND THAT THE SURVEY IS TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS SURVEY WAS MADE ON THE DAYS OF April 8 May, 1975.

DIN # 55758 - 1/1
APLS

ARIZONA DEPARTMENT OF ENVIRONMENTAL SERVICES
WATER QUALITY DIVISION - NON-POINT SOURCE SECTION
L-75-4831