LOT 16

LOT 15

LOT 14

N. SECOND Ave. ℄

32'

Reference Line of Survey 267.57' North to ℄ of Ave "A"

8'

Line

N.W. Cor of LOT 15, Blk. 13.

7.48

6.75'

6.75'

2.8

6.80

N. Line of LOT 15, BLOCK 13

Brick Wall

56' East of Rear Wall

Brick Wall

6.80

S.E. Cor. of LOT 16

S.E. Cor. of Building on Lot 16

6.75

7.48

Line

Brick Wall

10'

Reference Line of Survey

Ref. Line of Survey 267.57' North to ℄ of Ave "A"

Paved, ALLEY

470.16'

202.57' South to ℄ of Glendale Ave.

17.32'

16.95'

16.88'

Rear Wall 17.07'

17.6'

17.53'

202.59' S. to ℄ of Glendale Ave.

EAST Brick Wall

S.W. cor. of LOT 15, Blk 13.

S. LINE of LOT 15, BLOCK 13

S.E. Cor. of LOT 15

N.E. Cor. of Building on Lot 14

E. End of Building

Property

Property

SURVEY MAP

Showing Position of the Boundary Walls on the Side Lines of LOT 15, Block 13. Amended Plat of GLENDALE, ARIZ. BOOK 2, PAGE 49, M.C.R.

Wm. N. Bartlett Registered Land Surveyor.
31 S. 1st AVE., PHOENIX, ARIZONA.
Feb. 9 - 1955.

REGISTERED LAND SURVEYOR
CERTIFICATE EXPIRES
WM. N. BARTLETT
DEC 31 1955
ARIZONA, U. S. A.

DIN 59546