DIN# 62853-1

(37)

ARIZONA LAND SURVEY MONUMENT RECORD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
ARIZONA PROJECTS OFFICE
23636 N. 7TH STREET
P.O. BOX 9980
PHOENIX, ARIZONA 85068

DATE:

Filed as required by Arizona Revised Statutes, Section 33-106 (1972)

Sec. 1/4 10/15 Twp. 7N Range 1E G.&S.R.M.

County of Yavapai, State of Arizona

1. Type of Monument.
   1/4 COR. 10/15
2. Description of Evidence found.
   None Found
3. Description of Recovered, Rehabilitated, Restored or Re-established Monument.
   Set 30" alum. pipe w/ 3 1/4" USBR ALUM. CAP IN ground 20" - Built rock cairn around monument. Corner set by single proportion
4. Sketch of Monument and References.

Name Sam Felton

Date June 14, 1991

Book # 330-344 .01. 01 (d) .01 .08 26



Date, APR 10, 1991

STATION	DIST.	HORIZONTAL ANGLE	MAGNETIC BEARING	VERTICAL ANGLE	ELEVATION
	Continued from Page 15.				
⊼ C	CAS	160		H & T	
BS	NSFB-	37.			
FS 1)	11 ¼	S 15 T7N	R1E	SET 40 d	NAIL
	D	00-00-19.9	19.7		
	R	180-00-19.5 101-33-45.3			
	D	[illegible]-33-45.1	47.1'	MEAN & R	101-33-27.4'
	R	[illegible]			
	HORIZON	258-26-	26.3'		
	HORIZ	DIST	363.17		
2)	Stone	Possible ¼ cor -		8" x 8" above ground	
		Portion of	stone is	missing	
	D	00-00-10.2	10.2'		
	R	180-00-10.2	MEAN	92-35-	~~32.6~~ ~~27.4~~
	D	92-35-39.0	42.6 & R		32.6 4
	R	272-35-46.2		HORIZ DIST	366.84
				SLOPE DIST	378.95
	HORIZON	267-24-	32.1'	[illegible]	-95.03
				[illegible] 1	104-31-22.4
				[illegible] 2	255-28-38
				M	104-31-22