ARIZONA LAND SURVEY MONUMENT RECORD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
ARIZONA PROJECTS OFFICE
23636 N. 7TH STREET
P.O. BOX 9980
PHOENIX, ARIZONA 85068

(46)

Filed as required by Arizona Re·ised Statutes, Section 33-106 (1972)

DATE:

Sec. 25 Twp. 7S Range 8E G.&S.R.M.

County of PINAL, State of Arizona

DIN# 63033-1

1. Type of Monument. 25/36 SECTION CORNER

2. Description of Evidence found.
Fd two PK NAIL OFFSETS, one alum cap & rebar R.P. and one 60d nail

3. Description of Recovered, Rehabilitated, Restored or Re-established Monument.
Fd 60d nail's position to be that of correct position of sec. cor. Set 3¼" alum. cap & 30" alum. USBR pipe .50' +/- below ground. Corner fell on shoulder of road.

4. Sketch of Monument and References.

Name S. FELTON

Date SEPT 10 1992