(13)

ARIZONA LAND SURVEY MONUMENT RECORD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
ARIZONA PROJECTS OFFICE
23636 N. 7TH STREET
P.O. BOX 9980
PHOENIX, ARIZONA 85068

DATE:

Filed as required by Arizona Revised Statutes, Section 33-106 (1972)

Sec. 27 Twp. 7S Range 8E G.&S.R.M.

County of PINAL, State of Arizona

DIN# 63035-1

1. Type of Monument. 27 | 26 / 34 | 35 SECTION CORNER

2. Description of Evidence found.

Fd. Four Alum cap & Rebar "R.P."s & Four P.K. NAIL "cross-outs" in Houser Road

3. Description of Recovered, Rehabilitated, Restored or Re-established Monument.

SET 3¼" USBR Brass Disk & 2½' iron pipe flush w/ pavement, set in concrete, 1 FT. SQUARE

4. Sketch of Monument and References.

Name S. FELTON

Date SEPT 10 1992