ARIZONA LAND SURVEY MONUMENT RECORD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
ARIZONA PROJECTS OFFICE
23636 N. 7TH STREET
P.O. BOX 9980
PHOENIX, ARIZONA 85068

(48)

DATE:

Filed as required by Arizona Re·ised Statutes, Section 33-106 (1972)

Sec. 30 Twp. 7S Range 9E G.&S.R.M.

County of PINAL, State of Arizona

DIN# 63058-1

1. Type of Monument. 30/31 1/4 corner

2. Description of Evidence found.
Fd four alum. cap & rebar R.P.'s & Four PK nail "cross outs" in Houser Road

3. Description of Recovered, Rehabilitated, Restored or Re-established Monument.
Set 3¼" USBR brass disk & 2½' iron pipe flush w/ pavement, set in concrete, 1 FT. SQUARE.

4. Sketch of Monument and References.

Name S. FELTON

Date SEPT. 10, 1992