ARIZONA LAND SURVEY MONUMENT RECORD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
ARIZONA PROJECTS OFFICE
23636 N. 7TH STREET
P.O. BOX 9980
PHOENIX, ARIZONA 85068

(49)

Filed as required by Arizona Re·ised Statutes, Section 33-106 (1972)

DATE:

Sec. 30 Twp. 7S Range 9E G.&S.R.M.

County of PINAL, State of Arizona

DIN# 63059-1

1. Type of Monument. 30 | 29 / 31 | 32 SECTION CORNER

2. Description of Evidence found.
Fd four alum. cap & rebar R.P.'s & four PK nail cross outs in Houser Road

3. Description of Recovered, Rehabilitated, Restored or Re-established Monument.
Set 3¼" brass disk & 2½ FOOT LONG iron pipe flush w/ pavement set in concrete, 1 ft. square

4. Sketch of Monument and References.

Name S. FELTON

Date SEPT 10, 1992