ARIZONA LAND SURVEY MONUMENT RECORD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF RECLAMATION
ARIZONA PROJECTS OFFICE
23636 N. 7TH STREET
P.O. BOX 9980
PHOENIX, ARIZONA 85068

(47)

DATE:

Filed as required by Arizona Revised Statutes, Section 33-106 (1972)

Sec. 30 Twp. 7S Range 9E G.&S.R.M.

County of PINAL, State of Arizona

DIN# 63060-1

1. Type of Monument. 30 / 31 R8E 36 SEC. COR.

2. Description of Evidence found.
NONE FOUND

3. Description of Recovered, Rehabilitated, Restored or Re-established Monument.
SET 3¼" Alum CAP & 30" alum USBR Pipe 26" in ground - set by single proportion

4. Sketch of Monument and References.

Name S. FELTON

Date SEPT 10 1992



Date, 9-9, **19** 92

STATION	DIST.	HORIZONTAL ANGLE	MAGNETIC BEARING	VERTICAL ANGLE	ELEVATION
T@	25/30	T7S R8E	USBR ALUM. CAP		
BS	25/30	T7S R8E	USBR BRASS CAP		
FS	30/31	T7S R9E	SET USBR ALUM. CAP		
D	00-00-30.1		32.50		
R	180-00-34.9				
M	270-19-00.0				
D	270-19-30.2		32.50		
R	90-19-34.8				
HORIZOND	89-41-04.4				
HD	181.20				
SD					
ZD					
P					